HAER CAL 14-BISH.V, 5H-

HISTORIC AMERICAN ENGINEERING RECORD INDEX TO PHOTOGRAPHS

Bishop Creek Hydroelectric System, Plant 4 Worker Cottage (Building 117) Bishop Creek Bishop Vicinity Inyo County California

HAER No. CA-145-4-H

Gregory L. O'Loughlin, photographer		April, 1997
CA-145-4-H-1	EXTERIOR OVERVIEW OF PLANT 4 SHOWING BUILDING 117 AT PHOTO MAIN RESIDENTIAL STREET LOOKI OPPOSITE SIDE OF STREET). VIEW	RIGHT (LAST HOUSE ON ING LEFT TO RIGHT ON
CA-145-4-H-2	EXTERIOR FRONT (SOUTHEAST) SII SHOWING MAIN RESIDENTIAL STREE FOREGROUND, CEMENT-LAID ROCE FRONT OF HOUSE, AND CONCRETE FRONT PORCH AND DOOR. NOTE S REPLACEMENT FOR ORIGINAL DOO SUBSEQUENTLY BEEN REMODELED DOOR. VIEW TO NORTHWEST.	EET IN LOWER K RETAINING WALL IN STEPS AND WALKWAY TO LIDING GLASS DOOR OR WHICH HAS
CA-145-4-H-3	EXTERIOR BACK (NORTHWEST) AN HOUSE FROM BACK ALLEY. ENTRATHROUGH STEPS AND PORCH ON NOVIEW TO SOUTH.	ANCE TO KITCHEN IS
CA-145-4-H-4	EXTERIOR DETAIL OF FRONT PORCE SIDING, SOFFITED BOXED CORNICE SUPPORT, AND STICK BALASTRADE MEMBERS. VIEW TO NORTH.	E, SQUARE POST PORCH
CA-145-4-H-5	EXTERIOR OF FRONT AND SOUTHW SHOWING GABLE-ROOFED 1965 AD GLASS WINDOWS. VIEW TO NORTH	DITION WITH SLIDING-
CA-145-4-H-6	INTERIOR OF LIVING ROOM SHOWI KITCHEN AT PHOTO CENTER, FLUS	· · · · · · · · · · · · · · · · · · ·

GLAZING AT PHOTO RIGHT, AND OPEN PANELED DOOR TO

BISHOP CREEK HYDROELECTRIC SYSTEM, PLANT 4, WORKER COTTAGE (BUILDING 117 HAER No. CA-145-4-H INDEX TO PHOTOGRAPHS (Page 2)

BEDROOM NO. 2 AT LEFT PHOTO CENTER. DECORATIVE
WOOD STRIPPING ON WALLS AND CEILING IS CARRIED
THROUGHOUT REST OF ORIGINAL PORTION OF HOUSE. VIEW
TO NORTH.

	THROUGHOUT REST OF ORIGINAL PORTION OF HOUSE. VIEW TO NORTH.
CA- I45-4-H-7	INTERIOR OF LIVING ROOM SHOWING REMNANT OF ORIGINAL END WALL AND SMOOTH DRY-WALL FINISH OF 1965 ADDITION IN BACKGROUND. VIEW TO SOUTHWEST.
CA-145-4-H-8	INTERIOR OF KITCHEN SHOWING OPEN DOORWAY TO LIVING ROOM, AND KITCHEN CABINETS. VIEW TO SOUTH.
CA-14 5-4- H-9	INTERIOR OF KITCHEN SHOWING 1950s STYLE CABINETRY AND 3-LIGHT OVER 3-LIGHT, DOUBLE-HUNG, WOOD-FRAMED WINDOW OVER SINK, VIEW TO NORTH.
CA-I45-4-H-10	INTERIOR KITCHEN UTILITY AREA SHOWING PARTITION, PANELED AND GLAZED REAR DOOR, AND ROW OF 6-LIGHT OVER 1-LIGHT, DOUBLE-HUNG, WOOD-FRAMED WINDOWS AROUND EAST CORNER OF HOUSE. VIEW TO EAST.
CA-145-4-H-11	INTERIOR OF BEDROOM NO. 1 SHOWING OPEN DOOR TO KITCHEN AT PHOTO LEFT, OPEN DOOR TO WALK-IN CLOSET AT PHOTO LEFT CENTER, AND OPEN DOOR TO BATHROOM AT PHOTO RIGHT. VIEW TO SOUTH.
CA-145-4-H-12	INTERIOR OF BEDROOM NO. 1 SHOWING ORIGINAL 6-LIGHT OVER 1-LIGHT DOUBLE-HUNG, WOOD-FRAMED WINDOWS WITH SIMPLE WOOD SURROUNDS AND PROJECTING SILLS ON NORTHEAST AND NORTHWEST WALLS. VIEW TO NORTH.
CA-145-4-H-13	INTERIOR OF THE BATHROOM SHOWING OPEN DOOR TO BEDROOM NO. 1 AT PHOTO LEFT, AND BUILT-IN CABINET ABOVE TOILET AT PHOTO CENTER. VIEW TO NORTH.
CA-145-4-H-14	INTERIOR OF THE BATHROOM SHOWING OPEN DOOR TO BEDROOM NO. 2 AND BUILT-IN CABINET/VANITY ADJACENT TO THE SINK. VIEW TO SOUTH.

INTERIOR OF BEDROOM NO. 2 SHOWING OPEN PANELED DOOR

CLOSET AT RIGHT OF THE BATHROOM DOOR, AND OPEN DOOR

TO THE BATHROOM AT PHOTO CENTER, OPEN DOOR TO

CA-I45-4-H-15

BISHOP CREEK HYDROELECTRIC SYSTEM, PLANT 4, WORKER COTTAGE (BUILDING 117 HAER No. CA-145-4-H INDEX TO PHOTOGRAPHS (Page 3)

TO LIVING ROOM AT EXTREME PHOTO RIGHT. VIEW TO NORTH.

CA-145-4-H-16

INTERIOR OF BEDROOM NO. 3 (1965 ADDITION). OPEN DOOR LEADS TO BEDROOM NO. 2. WALLS AND CEILING IN THIS ROOM DO NOT HAVE THE DECORATIVE WOOD STRIPPING FOUND IN THE ORIGINAL PORTIONS OF THE HOUSE. VIEW TO NORTHEAST.

CA-145-4-H-17

INTERIOR OF BEDROOM NO. 3 SHOWING MODERN ALUMINUM-FRAMED SLIDING-GLASS WINDOWS WITH WOOD SURROUNDS ON SOUTHWEST AND NORTHWEST WALLS. VIEW TO WEST.